

GI Inspection, Tracking, Reporting-MS4 Permit Expectations

Jacob Zimmerman, PE

5/22/19






Permit Requirements

- Meet 20% TSS Reduction
 - Maintain all BMPs which achieve 20% goal
- Meet TMDL Reach Reductions
 - Goal is to delist the waters
- Pollution Prevention
 - Inspection and maintenance frequencies



DNR Expectations

1. Program or Plan which describes inspections and maintenance
2. Implementation of that program
3. Reporting



WISCONSIN
DEPT. OF NATURAL RESOURCES



WHY?

- Required By Permit
- Water quality improvement
 - Models assume optimal pollutant reduction