

**MILWAUKEE TRANSPORT SERVICES, INC.**

Tuesday, September 15, 2020

**ADDENDUM NO:** 1

**BID NO:** 2020-19 Dock Repairs

**OPENING DATE:** September 24, 2020 @ 2:00 PM, CST

1. alternate for dock bumpers:

<https://www.multi-fab.com/dock-parts-accessories/dock-categories/bumpers-and-wheel-chocks/rubber-laminated-bumpers>

Answer: Multi-Fab products rubber laminated bumpers MFRL are approved as an equal. Poweramp McGuire DLM are approved equal dock bumpers.

2. Alternate for dock seals – attachment -NOVA Technology Dock seals & shelters –

Answer: Nova Technology FPH series approved as an equal dock seal.

3. General Scope #10 - Please confirm you want outside wall to outside wall painted - not just where patched.

Answer: Hired vendor will only paint both sides of the patched area; this should be done prior to reinstallation of the components. The paint color for the CMU will need to be selected on site later, when this is under construction.

4. On the outside of the dock bay, in both corners where the adjacent wall comes in, they have cracking - is this supposed to be addressed?

Answer: These cracks will be addressed in a separate forthcoming bid for repair work; no work at this time.

5. Can we use MTS's scissors lift?

Answer: No, vendor will need to provide lift.

---

**BID NO: 2020-19**

Please sign and return one copy with the bid Documents.

We acknowledge receipt of Addendum #1.

---

Name

---

Company Name

---

Signature

---

Date