

# Zoo Interchange


## STH 100 Reconstruction (2013)

### Construction Detours

West Leg Closure of Hwy 100 & Bluemound Rd Intersection

#### Legend

-  - Full Closure
  -  - Roadway Under Construction (Open to Traffic)
  -  - Long Term Ramp Closure
- Full Closure Construction Detour Routes**
-  - EB Bluemound Rd Primary Detour Route
  -  - EB Bluemound Rd Secondary Detour Route
  -  - WB Bluemound Rd Primary Detour Route
  -  - WB Bluemound Rd Secondary Detour Route
-  - Existing Traffic Signal
  -  - Temporary Traffic Signal
-  - Local Roads
  -  - Freeway Mainline, Entr/Exit & System Ramps



DRAFT  
v4 7/9/13

Detour routes shown are based on the  
January 8, 2013 LET Plans

